

# Verification by the loss of humic scraper scratch coating

Abrasion of glass by scraper sharpener



Coating is damaged by the loss of humic

